Approved For Release 2006/04/20 : CIA-RDP82-00457R015300450010-6

INFORMATION REPORT

CD NO.

COUNTRY

East Germany

DATE DISTR. 29 December 1952

SUBJECT

Shortage of P-2 Iron in East Germany

PLACE

NO. OF PAGES

ACQUIRED

DATE OF

INFO.

25X1A

NO. OF ENCLS.

SUPPLEMENT TO REPORT NO.

25X1

25X1

e.s. C., 31 and 88, as abended. Its transcribeion of its contents in art manner to an unauthorit hibited by Law. Reproduction of this form is pi production () and ()

THIS IS UNEVALUATED INFORMATION

DO ROY GIRCULATE

- The shortage of P 2 iron (aluminum-plated iron plates) for the radio tube industry was discussed at a merting of the Pachkommission (Fako) fuer Elektronenroebren (Commission of Experts for Electron Tuber) hold on 29 Aurust 1952. It was decided to organize a four man collective responsible for the procurement of P 2 iron from Hanau. The collective was promised a special bonus if it succeeded in obtaining this material. The following dable was also sent to the Deputy Minister President Heinrich wau: "The entire electron tube industry, radio tube industry, industry for measuring instruments, and industry for electro-acoustic apparatus will have to cease production unless 800 tons of P 2 iron can be procured immediately from West Germany. At least 15 percent of the powdered from (Vakunmschmelse) must be imported from Hanau in order to meet the most urgent requirements."
- 2. So far, all attempts to meet the ? 2 iron requirements in East Germany have been unsuccessful. The naterial supplied by the Auerhanner Plant is too hard-Therefore, the Berlin Metal Works and Metallurgical Plant in Berlin-Wiederschoeneweide were assigned to experiment with the production of P 2 iron.
- It was feared that the HF Plant (OSN) would experience considerable production difficulties in late September 1952 as sources for the urgently required supplies of P 2 iron have not yet been found.
- 4. The average stocks of P2 iron stored in the HF Plant in Aurust 1952 were sufficient for only 12 days requirements.

CLASSIFICATION SECRET

NAVY NSRB DISTRIBUTION AIR.